PCB Failure Analysis and Diagnostics

This comprehensive guide delivers a structured, six-step FA workflow, deep dives into critical mechanisms (CAF, Solder Fatigue, EOS), and practical application strategies for advanced non-destructive (NDI) and destructive (DPA) tools like TDR, C-SAM, and FIB. Learn how to translate technical findings into SMART Corrective Actions, ensuring definitive root cause resolution and immediate improvements in product reliability.



DOCUMENT METADATA

Field	Detail
Title	PCB Failure Analysis: Methodology, Mechanisms, and Advanced Diagnostic Techniques
Document Revision	1.1 (Dynamic Edition)
Date of Issue	Feb 2025
Prepared by	Shenzhen Well Done PCB Limited

Table of Contents

1.0 🚀 Introduction and Core Mission

This document provides a systematic framework and essential methodologies for performing Printed Circuit Board (PCB) failure analysis (FA). Our mission is clear: to move beyond simply repairing symptoms and **definitively identify the Root Cause.**

> 🎯 **Core Goal of FA:** To determine the precise **Root Cause** of a product failure, enabling corrective actions in design, manufacturing, or material selection, thereby improving product reliability and drastically reducing long-term costs.

1.1 Scope and Coverage

This guide covers the standard FA workflow, common failure modes encountered in PCB assemblies (PCBA), and the necessary **non-destructive (NDI)** and **destructive (DPA)** analytical techniques required for a comprehensive, evidence-based investigation.

1.2 Safety Precaution

Safety First! All laboratory personnel must strictly observe basic safety rules. Prior to handling any unit, ensure the failed unit is **safely depowered**, discharge any high-capacitance components, and handle chemicals used in destructive analysis with appropriate **Personal Protective Equipment (PPE)**.

2.0 ⚙️ The Systematic Failure Analysis Workflow

A structured, methodical approach is **non-negotiable** for successful failure analysis. We mandate a rigid progression from non-destructive methods to highly destructive ones to ensure evidence preservation.

Step	Phase	Action & Goal	Primary Tools
1️⃣ **Verification**	**Data Collection**	Confirm the reported failure mode. Collect **all historical data** (schematics, LOT info, environment logs).	Test Reports, DMM
2️⃣ **NDI**	**Non-Destructive**	Visual inspection,	Optical Scope,

	Inspection	then use advanced NDI to localize faults **without altering the board**.	X-Ray, **C-SAM**
3 **Localization**	**Electrical Pinpointing**	Pinpoint the **exact location** of the electrical anomaly (e.g., short, leakage).	Thermal Camera, **TDR**, **IVCT**
4 **DPA**	**Destructive Physical Analysis**	Cross-sectioning and material analysis to observe the defect area structurally and chemically.	Micro-sectioning, **SEM/EDS**, **FIB**
5 **Root Cause**	**Conclusion**	Correlate **all findings** (electrical, visual, structural) to determine the precise initiating mechanism of failure.	Analytical Interpretation
6 **Reporting**	**Actionable Intelligence**	Document findings, root cause, and specific recommendations for process or design changes.	Comprehensive FA Report

3.0 🔥 Common PCB and PCBA Failure Mechanisms

Failures are generally categorized into Electrical, Thermal, Mechanical, and Chemical causes. Understanding the mechanism is key to choosing the right tool.

3.1 Thermal Failures 🔥

Mechanism	Description	Detection/Observation
CAF (Conductive Anodic Filament)	Electrochemical migration along glass fibers, forming a conductive path (short) in the presence of moisture and voltage, accelerated by heat.	Micro-sectioning shows dark filament in glass weave. Electrical leakage.
Delamination	Separation of the copper foil from the substrate or separation between laminate layers.	Visible bubbles or swelling (**Blisters**). Detected via **C-SAM**.
Measling/Blistering	White spots (measling) or localized swelling (blistering) due to localized separation of the substrate layers.	Visual Inspection.

3.1.1 🔬 Detailed Look at CAF (Conductive Anodic Filament)

CAF is an insidious electrochemical failure mode unique to glass-reinforced materials (like FR4). It requires three critical conditions: **Moisture, Ionic Contaminants, and DC Voltage Bias.**

> ⚠️ **Failure Process:** Copper ions () migrate along the glass fiber-to-resin interface toward the cathode, where they form a **conductive filament** that shorts the circuit. The characteristic signature is a low-resistance short or high-leakage current.

3.1.2 CAF Prevention Strategies 🛡️

Mitigating CAF involves breaking one or more of the three critical failure conditions.

Strategy Category	Key Actions	Impact
Material Selection	Use laminates with **higher** and better resin systems (e.g., polyimide).	Reduces moisture absorption and increases glass-fiber adhesion.
Design Practices	Maximize spacing between plated features (vias, PTHs).	Lowers the **electric field gradient**, reducing the driving force for ion migration.
Manufacturing Control	Optimize the drilling process to prevent glass fiber damage (known as "**smear**").	Damaged fibers are easier conduits for moisture/ion transport.
Environmental Control	Apply moisture barrier coatings and control humidity in storage/operation.	Eliminates the ionic transport medium (moisture).

3.2 Electrical and Electromigration Failures ⚡

Mechanism	Description	Root Cause Indicators
EOS (Electrical Overstress)	Damage caused by excessive current or voltage, resulting in localized heating and irreversible change.	Physical damage, **charred components**, melted metal traces.
ESD (Electrostatic Discharge)	Transient high voltage pulse leading to immediate or latent damage to sensitive ICs or traces.	Microscopic pitting on component surface.
Solder Joint Fatigue	Cracking in solder joints due to **CTE mismatch** and thermal cycling.	X-Ray and micro-sectioning reveal cracks near the **IMC layer**.

3.3 Contamination and Corrosion 🧪

Mechanism	Description	Detection/Observation
Dendrite Growth	Metal migration (usually copper or tin) across an insulation barrier, forming tree-like conductive paths (short).	Visual inspection shows metal whiskers or dendrites.
Corrosion	Chemical attack of metal surfaces, leading to open circuits or high resistance.	Discoloration, **pitting**, and etching of traces or pads.

4.0 🔬 Key Analytical Tools and Techniques

The choice of tool is dictated by the failure type and the stage of analysis. **NDI MUST precede DPA.**

4.1 Non-Destructive Techniques (NDI) 🔍

Tool	Principle	Primary Application in FA
Optical Microscope	Visible light magnification.	Surface inspection for cracks, contamination, lifted pads.
X-Ray / CT Scan	Uses X-rays based on density differences.	Inspecting hidden solder joints (BGA/QFN) for voids, shorts, or opens.
Thermal Imaging Camera	Detects infrared heat.	Localizing short circuits or high-resistance paths by observing localized heat spikes under power.

4.1.1 Detailed Look at C-SAM (Scanning Acoustic Microscopy) 🔊

C-SAM is the primary tool for assessing bond integrity.

- **Principle:** Uses high-frequency ultrasound. A strong reflection occurs when the acoustic

pulse encounters a change in **acoustic impedance**, most notably **air gaps** (voids, cracks, delamination).

- **Key Detection:** Delamination (layer separation), **Popcorning** (component package voids), and non-bonds in underfill.

4.1.2 Detailed Look at TDR (Time-Domain Reflectometry) 📡

TDR is essential for **electrical localization** in complex multilayer PCBs.

- **Principle:** Injects a fast voltage pulse into a line. Reflections occur when the pulse encounters any change in the **characteristic impedance ()**.
- **Calculation:** The distance to the fault is determined by the time delay () of the reflected pulse.

  📊 **TDR Fault Identification:**

  - **Open Circuit (Break):** Positive reflection that steps up. (Impedance)
  - **Short Circuit (Short):** Negative reflection that drops to zero. (Impedance)

4.1.3 Detailed Look at IV Curve Tracer (IVCT) 💡

IVCT is a powerful, **powered-off** diagnostic technique (V-I Signature Analysis).

- **Principle:** Applies a low-level **AC voltage sweep** between two test points, plotting Voltage vs. Current to generate a V-I **Signature**.
- **Application:** Comparing the signature of a **Failed Unit (FU)** against a **Known Good Unit (KGU)** instantly reveals deviations caused by component damage or subtle manufacturing defects.

Signature Shape	Interpretation/Fault
Straight Line (slope)	Purely Resistive (e.g., resistor)
Vertical Line (slope)	**Dead Short** (Low Resistance)
Horizontal Line (slope)	**Open Circuit** (High Impedance/Lifted Pin)
Bent/Stepped Curve	Semiconductor Junction (Diode/Transistor)

4.2 Destructive Physical Analysis (DPA) 🔪

Tool	Principle	Key Insight Gained
Micro-Sectioning	Grinding and polishing the sample to expose the defect in cross-section.	**Definitive view** of plating quality, layer registration, and solder joint integrity.

SEM	Scanning Electron Microscope.	High-magnification image of fracture surfaces and micro-scale physical defects.
EDS	Energy-Dispersive X-ray Spectroscopy.	**Elemental Composition** (Identifying unknown contaminants or material anomalies).
FIB	Focused Ion Beam (typically Gallium ions).	**Nanoscale precision** milling/cross-sectioning for ultra-thin samples.

4.2.1 🛠️ Detailed Procedure for Micro-Sectioning

Micro-sectioning is precision surgery on the PCB.

1. **Decapitation and Cutting:** Carefully cut a small coupon containing the failure site.
2. **Mounting (Potting):** Embed the coupon in epoxy, ensuring perfect perpendicularity.
3. **Grinding & Polishing:** Use progressively finer abrasives to create a mirror-like finish, stopping *exactly* at the defect plane.
4. **Etching (Optional):** Mild chemical etchants highlight grain structure and stress lines.

4.2.2 🔬 Post-Sectioning Analysis: SEM and EDS

- **SEM Imaging:** Confirms the structural defect **morphology** (shape and structure) at very high magnification.
- **EDS Analysis:** Confirms the **material origin** (chemical composition). Essential for confirming elements like **Chlorine (Cl)** or **Bromine (Br)** in corrosive residue.

5.0 ✅ Failure Analysis Reporting: Practical Guidance

The final FA report translates technical facts into **actionable business intelligence.**

5.1 Key Report Components & Audience Focus

Report Section	Core Content	Emphasis for Management
Executive Summary	What failed, **Why it failed (Root Cause)**, and Corrective Action.	Clarity of **cost/risk reduction** and impact timeline.
Analysis Results	Detailed chronological findings (NDI DPA) and all supporting images.	**Visual proof of the defect** (high-impact image).
Root Cause Conclusion	Clear logical argument connecting the defect to the design/manufacturing deficiency.	**Definitive, non-ambiguous determination of fault responsibility.**
Corrective Actions	Specific recommendations to prevent recurrence.	Clear assignment of responsibility and implementation deadline (**SMART** goal).

5.3 Formulating SMART Corrective Actions 🚀

Recommendations are the most critical part of the report. They **MUST** adhere to the **SMART** criteria: Specific, Measurable, Achievable, Relevant, and Time-bound.

Criteria	Explanation	Example (Failure: Insufficient Solder Fill)
Specific	Define *what* needs to be changed and *where*.	**Action:** Increase copper plating thickness in microvias by .
Measurable	The result must be quantifiable to track effectiveness.	**Target:** Achieve a minimum via barrel wall thickness of in all future lots.

Achievable	The change must be physically and economically realistic.	**Verification:** Work with plating supplier to confirm feasibility.
Relevant	The action must directly address the identified root cause.	**Direct Impact:** Mitigates the low conductivity/open risk caused by thin plating.
Time-bound	Assign a deadline for implementation and verification.	**Deadline:** New plating specification enforced starting with LOT Q3-2026.

6.0 💡 Practical FA Case Study: BGA Delamination (Popcorning)

Symptom: BGA component shows intermittent electrical opens after thermal cycling.

Workflow Step	Action Taken	Key Observation/Finding
Verification	Electrical testing.	Intermittent open on corner balls, failure is heat-related.
NDI: C-SAM	Focused acoustic scan on the BGA interface.	**Strong acoustic reflection detected** under the package body and in the PCB laminate, indicating **delamination/non-bond**.
DPA: Micro-Section	Sample sectioned through the delaminated area.	Revealed a **crack extending from the top PCB surface** propagating inward towards a copper plane.
Root Cause	Analysis of combined data.	The **moisture-saturated PCB laminate** experienced

		rapid heating (improper MSL handling), causing trapped moisture to vaporize and expand, leading to a permanent **internal delamination (popcorning)**.
Corrective Action	Recommended changes.	Mandate higher pre-bake times/temperatures and improve long-term storage and handling protocols.

7.0 🔮 Conclusion and Future Outlook

Successful PCB Failure Analysis is paramount for product reliability and cost control. By strictly adhering to the systematic six-step workflow—progressing from non-destructive verification through to definitive destructive analysis—engineers can accurately pinpoint the root cause of complex failures.

> ⭐ **Key Takeaway:** The final and most crucial step is the implementation of **SMART Corrective Actions**. These actions must translate technical findings into measurable process and design improvements. Continued investment in advanced FA tooling (like FIB and high-resolution SEM) is essential to meet the reliability demands of modern high-density, high-speed electronic systems.